

# IMPORTANT SAFETY RECALL

NHTSA Recall No. 25E036

May 2025

Dear Holley Performance Brands Dealer:

We are writing to inform you that Holley is conducting a voluntary safety recall of certain fuel pressure regulators (identified in the table below) in response to a discovery that some of these parts do not meet dimensional requirements. As we have learned that this condition may potentially cause damage to the diaphragm and lead to a fuel leak, Holley is initiating a recall to address this situation. Our records indicate that recalled products were shipped to you.

## What Products are Involved?

This recall involves the following fuel pressure regulators and fuel pressure regulator/plumbing kits:

| Part Number | Part Description                         |
|-------------|------------------------------------------|
| 12-881      | BP Regulator 6 PSI                       |
| 12-881KIT   | 12-881 Regulator Kit, Gauge and Fittings |
| 12-886      | BP Regulator 59.5 PSI BLK                |
| 12-886KIT   | 12-886 Regulator Kit, Gauge and Fittings |
| 526-24      | G Body Fuel Plumbing Kit Return          |
| 526-25      | Fuel Kit, Fox Body, 6AN                  |
| 12-887      | BP Regulator 6 PSI BLK                   |
| 12-887KIT   | 12-887 Regulator Kit, Gauge and Fittings |


This recall only involves the above part numbers with a box date code of 140'24 or LATER (where "140" is the day of the year and "24" is the two-digit year).

The part number and box date code can be found as follows (part number 12-886 shown below):

On the box:



On the fuel pressure regulator:



Holley previously requested that you quarantine your inventory of these parts per the enclosed "Stop Sale Notice to Distribution Partners"

## What is the Problem?

Holley has determined that a small subpopulation of these products may not meet dimensional requirements. As a consequence, the diaphragm may become susceptible to damage during operation, potentially leading to a fuel leak. A fuel leak in the presence of an ignition source may increase the risk of a fire.

## What should you do?

- (a) **Product Remaining in Your Inventory:** If any fuel pressure regulators or fuel pressure regulator kits (as identified by the part numbers and identifying marks) remain in your inventory, you should return the kit to Holley for an exchange. Please contact Holley Customer Service at 1-800-638-0032 or by email at [returns@holley.com](mailto:returns@holley.com). We will issue you a Returned Goods Authorization (RGA) number and process a restocking order for any recall-related SKUs.

***Note: It is a violation of federal law to sell the recalled products.***

- (b) **Products You Sold to Other Resellers or Installers:** If you sold the recalled fuel pressure regulators or fuel pressure regulator kits to reselling customers or installers, you must forward a copy of this letter and enclosed NHTSA-approved "Owner Letter" to them within five (5) business days of receipt. Recalled products should be returned to you, as the original point of purchase, for an exchange OR the reseller can contact Holley Customer Service at 1-800-638-0032 or [returns@holley.com](mailto:returns@holley.com), and we will issue them a Return Goods Authorization (RGA) number and process a restocking order for any recall-related SKUs.

- (c) **Products You Installed or Sold to Consumers:** You must immediately check your sale records to identify any consumers to whom you sold the recalled parts and send them a copy of the enclosed NHTSA-approved Owner Letter. Alternatively, you can email your customers' contact information to Holley at [returns@holley.com](mailto:returns@holley.com) and we will contact them directly.

- End Consumers will be instructed to contact Holley Customer Service at 1-800-638-0032 or [returns@holley.com](mailto:returns@holley.com). Once the fuel pressure regulator part number and/or identification marks have been confirmed, Customer Service will coordinate the return, send a return shipping label, and process an order for a replacement unit.

If you have any questions, please contact Customer Service at 1-800-638-0032 or [returns@holley.com](mailto:returns@holley.com).

We apologize for any inconvenience this may cause, but we are taking this action in the interest of our customers' personal safety and satisfaction with our products.

Sincerely,



Enclosures (Owner Letter; Identification Guide; Stop Sale Notice to Distribution Partner)

# IMPORTANT SAFETY RECALL

NHTSA Recall No. 25E036

May 2025

Dear Holley Performance Brands Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Holley Performance Brands has decided that a defect which relates to motor vehicle safety exists in certain Holley Branded Fuel Pressure Regulators identified below. We are conducting a safety recall to address the issue. You are receiving this letter because retailer records indicate that you may have purchased one of these parts.

## What Products are Involved?

This recall involves the following fuel pressure regulators and fuel pressure regulator/plumbing kits:

| Part Number | Part Description                         |
|-------------|------------------------------------------|
| 12-881      | BP Regulator 6 PSI                       |
| 12-881KIT   | 12-881 Regulator Kit, Gauge and Fittings |
| 12-886      | BP Regulator 59.5 PSI BLK                |
| 12-886KIT   | 12-886 Regulator Kit, Gauge and Fittings |
| 526-24      | G Body Fuel Plumbing Kit Return          |
| 526-25      | Fuel Kit, Fox Body, 6AN                  |
| 12-887      | BP Regulator 6 PSI BLK                   |
| 12-887KIT   | 12-887 Regulator Kit, Gauge and Fittings |


This recall only involves the above part numbers with a box date code of 140'24 or LATER (where "140" is the day of the year and "24" is the two-digit year).

The part number and box date code can be found as follows (part number 12-886 shown below):

On the box:



On the fuel pressure regulator:



## What is the Problem?

Holley has determined that a small subpopulation of these products may not meet dimensional requirements. As a consequence, the diaphragm may become susceptible to damage during operation, potentially leading to a fuel leak. A fuel leak in the presence of an ignition source may increase the risk of a fire.

## What should you do?

- Step 1 – Verify you purchased one of the affected Holley Fuel Pressure Regulators listed in the table above
  - This would be the part number of the kit you purchased from Holley or a Holley dealer.
  - Regulators purchased before August 2024 are not affected
- Step 2 – Verify if your unit is affected by this recall:
  - Using the enclosed Identification Guide, compare your Holley fuel pressure regulator or packaging to the image and information provided in the guide. This guide will assist you in determining whether your regulator is a recalled unit. If your product is affected, proceed to Step 3.
- Step 3 – Contact Holley Customer Service at 1-800-638-0032 or [returns@holley.com](mailto:returns@holley.com)
  - A Holley Customer Service representative will:
    - Gather your contact information (name, address, phone number, email address)
    - Verify your unit is a recalled unit
    - Coordinate a Return Goods Authorization (RGA) number for the recalled unit
    - Arrange for free shipping pickup of the defective unit – a shipping label will be provided
    - Place an order for a free replacement unit to get you back on the road
- Step 4 – Package your regulator or fuel kit for return to Holley
  - If your regulator or fuel system kit is brand new and still in the original packaging:
    - Remove the box containing the Holley fuel pressure regulator (if in a kit)
    - Place the box containing the fuel pressure regulator in another overpack box to protect the unit
    - Write the Return Goods Authorization number on the box in large black letters
    - Affix the shipping label and prepare for UPS pickup or drop-off
  - If your fuel pressure regulator or plumbing kit is already installed on your vehicle:
    - Disconnect the fuel system regulator from all fuel lines and vacuum/boost lines
    - Remove your fittings from the regulator and drain any remaining fuel
    - Place the regulator in a ziplock-type bag to prevent fuel leakage in shipment
    - Package the regulator in a protective box
    - Write the RGA number on the OUTSIDE of the box in large black letters
    - Affix the shipping label and prepare for UPS pickup or drop-off

## Questions or Concerns?

If you have any questions regarding this recall, you may contact Holley Customer Service at 1-800-638-0032 or [returns@holley.com](mailto:returns@holley.com). If you are unable to obtain a remedy without charge within a reasonable time, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We apologize for any inconvenience this may cause, but we are taking this action in the interest of your personal safety and satisfaction with our products.

Sincerely,



Enclosures (Guidelines for Identifying Recalled and NON-Recalled Fuel Pressure Regulators)

# Guidelines for Identifying RECALLED Fuel Pressure Regulators vs NON-RECALLED Fuel Pressure Regulators



Recall No. 25E036


## Identifying a RECALLED Regulator

- Verify that the fuel pressure regulator part number is one of the following: 12-881, 12-886, or 12-887; or that the kit number is one of the following: 12-881KIT, 12-886KIT, 526-24, 526-25 or 12-887KIT
- Box Julian Date Code is LATER than 139'24 ("139" is the day of the year, "24" is the two-digit year)
  - Example - 225'24 or 43'25 would be later than 139'24
- Red caps on the ports
- Box states "Made in Thailand" on side
- Holley Logo Cast into the back of the regulator



Date Code  
Later than  
139'24





If the regulator and / or packaging has the characteristics shown above, the regulator is a potentially defective unit and part of the recall – follow directions above (“What Should You Do?”) to return the product to Holley

Intentionally Left Blank – See more information below


## Identifying a NON-RECALLED Regulator

- If the fuel pressure regulator part number is other than 12-881, 12-886, or 12-887, or the kit number is other than 12-881KIT, 12-886KIT, 526-24, 526-25 or 12-887KIT, the part is not part of the recall.
- If the fuel pressure regulator part number or kit number is one of the above, inspect the regulator box and the regulator itself for the following, any of which will indicate a NON-RECALLED part:
  - Box Julian Date Code is 139'24 or EARLIER ("139" is the day of the year, "24" is the two-digit year)
    - Example - 225'23 or 43'24 would be earlier than 139'24
  - Blue caps on the ports
  - Box states "Made in Korea" on side and on UPC label
  - NO Holley Logo cast into the back of the regulator




Date Code  
of 139'24 or  
Earlier


Made in  
Korea on  
UPC Label



Blue Caps



NO Holley Logo  
Cast in Back of  
Regulator



If the regulator and/or packaging has any of the characteristics shown above, the regulator is a NOT part of the recall and does not need to be returned

Intentionally Left Blank



## IMPORTANT STOP SALE NOTICE TO DISTRIBUTION PARTNERS

Dear Holley Performance Brands Distribution Partners:

Holley places a high priority on safety and recently conducted an investigation of certain Fuel Pressure Regulators listed in the table below in response to a product quality issue. Specifically, Holley determined that these products, which were manufactured by a third party, do not meet dimensional requirements. While Holley's incident rate has been low to date, we take these issues very seriously and will continue to investigate and track issue frequency. As we have learned that this condition may potentially cause damage to the diaphragm and lead to a fuel leak, Holley is initiating this stop sale to address this situation.

At this time, we believe the below parts and kits to be impacted:

| Part Number | Part Description                         |
|-------------|------------------------------------------|
| 12-881      | BP Regulator 6 PSI                       |
| 12-881KIT   | 12-881 Regulator Kit, Gauge and Fittings |
| 12-886      | BP Regulator 59.5 PSI BLK                |
| 12-886KIT   | 12-886 Regulator Kit, Gauge and Fittings |
| 526-24      | G Body Fuel Plumbing Kit Return          |
| 526-25      | Fuel Kit, Fox Body, 6AN                  |
| 12-887      | BP Regulator 6 PSI BLK                   |
| 12-887KIT   | 12-887 Regulator Kit, Gauge and Fittings |

Holley is preparing its report to the National Highway Traffic Safety Administration (NHTSA) to initiate a formal recall of these products. We are sending you this preliminary notification so that you can take initial steps to reduce the risk to our customers and prepare for the return of the impacted products. We will follow up soon with a more formal notification containing detailed instructions, including a form letter that dealers should use to notify their customers.

Our quality and supply chain teams are conducting additional investigations on the date codes associated with this quality issue. For now, we request that you immediately review all inventory of the part numbers listed above and quarantine all parts identified on that list, regardless of date code or receipt date. We will provide additional clarity on scope of date codes and return instructions in our follow-up communication.



We understand that this is an unfortunate situation, especially given the timing of the Holley Memorial Day Sale. Below is a recommended cross reference to substitute regulators that are not affected by this recall:

| Impacted Part Number on Hold | Best Match-Premium                      | Alternative with Different Fitting Sizes | Premium Replacement                                    | Good Match-No Pressure Gauge Port                 | Good Match-No Pressure Gauge Port                      | Sniper Specific          |
|------------------------------|-----------------------------------------|------------------------------------------|--------------------------------------------------------|---------------------------------------------------|--------------------------------------------------------|--------------------------|
|                              | Billet Universal Regulator 3/8" NPT I/O | Billet Universal Regulator with 6AN I/O  | Billet Replacement for Carburetors (3/8" NPT Fittings) | Direct Replacement for Carburetors (3/8 Fittings) | Direct Replacement for Carburetors (3/8" NPT Fittings) | Sniper EFI Regulator 6AN |
| 12-881                       | 12-879                                  | 12-880                                   | 12-841                                                 | 2015                                              | 12-803BP                                               |                          |
| 12-881KIT                    | 12-879KIT                               | 12-880KIT                                | 12-841KIT                                              |                                                   |                                                        |                          |
| 12-886                       | 12-879                                  | 12-880                                   |                                                        |                                                   |                                                        | 12-893                   |
| 12-886KIT                    | 12-879KIT                               | 12-880KIT                                |                                                        |                                                   |                                                        |                          |
| 12-887                       | 12-879                                  | 12-880                                   | 12-841                                                 | 2015                                              | 12-803BP                                               |                          |
| 12-887KIT                    | 12-879KIT                               | 12-880KIT                                | 12-841KIT                                              |                                                   |                                                        |                          |
| 526-24                       | No Kit Available                        |                                          |                                                        |                                                   |                                                        |                          |
| 526-25                       | No Kit Available                        |                                          |                                                        |                                                   |                                                        |                          |

We also request that you review your sales records to identify any consumers (or other downstream purchasers) to whom you sold the impacted parts identified above. Our follow-up notification will include a NHTSA-approved form letter to be used to notify these consumers.

If you have any questions, please contact me at [alexbuccilli@holley.com](mailto:alexbuccilli@holley.com).

Thank you for your continued support.

Sincerely,

Alex Buccilli  
SVP, Operations and Supply Chain