



IMPORTANT STOP SALE NOTICE TO DISTRIBUTION PARTNERS

Dear Holley Performance Brands Distribution Partners:

Holley places a high priority on product quality and performance. We are conducting a preliminary investigation of certain carburetors listed in the table below in response to a sourced component quality issue we identified internally during routine line testing. Specifically, Holley determined that the vacuum secondary throttle lever thickness may not meet dimensional requirements. While Holley is not aware of any related field failures or customer complaints, we take quality very seriously and are continuing to investigate the potential consequences of this condition, including whether it may cause a malfunction of the throttle linkage. Accordingly, Holley is initiating this stop sale notice to contain potentially impacted products while we conclude our investigation.

At this time, the below parts with invoice dates between February 24, 2026 and July 24, 2026 may potentially be impacted:

Item number	Item Description
0-8007	Holley Classic Carburetor - 390 CFM - 4160 - Gold Dichromate
0-8007-1	Holley Classic Carburetor - 390 CFM - 4160C - Polished/Gold Dichromate
0-1848-2	Holley Classic Carburetor - 465 CFM - 4160 - Gold Dichromate
0-1850C	Holley Classic Carburetor - 600 CFM - 4160 - Gold Dichromate
0-80458SA	Holley Classic Carburetor - 600 CFM - 4160 - Shiny
0-80783C	Holley Classic Carburetor - 650 CFM - 4150 - Gold Dichromate
0-3310C	Holley Classic Carburetor - 750 CFM - 4160 - Gold Dichromate
0-80508S	Holley Classic Carburetor - 750 CFM - 4160 - Shiny
0-3310S	Holley Classic Carburetor - 750 CFM - 4160 - Shiny
0-80459SA	Holley Classic Carburetor - 750 CFM - 4160 - Shiny
0-80531	Holley Classic Carburetor - 850 CFM - 4150 - Gold Dichromate
0-3370	Holley Classic Carburetor - Model 4160 585 CFM
0-82570	Holley Marine Avenger Carburetor - 570 CFM - 4150
0-82670	Holley Marine Avenger Carburetor - 670 CFM - 4150
0-82770	Holley Marine Avenger Carburetor - 770 CFM - 4150
0-80570	Holley Street Avenger Carburetor - 570 CFM - 4150 - Shiny
0-81570	Holley Street Avenger Carburetor - 570 CFM - 4150 - Shiny
0-80670	Holley Street Avenger Carburetor - 670 CFM - 4150 - Polished
0-81670	Holley Street Avenger Carburetor - 670 CFM - 4150 - Shiny
0-80770	Holley Street Avenger Carburetor - 770 CFM - 4150 - Shiny
0-83770	Holley Street Avenger Carburetor - 770 CFM - 4150 - Shiny
0-80870	Holley Street Avenger Carburetor - 870 CFM - 4150 - Shiny
0-83870	Holley Street Avenger Carburetor - 870 CFM - 4150 - Shiny
0-82750SA	Holley Street HP Carburetor - 750 CFM - 4150 - Shiny
0-90670	Holley Truck Avenger Carburetor - 670 CFM - 4150 - Gold Dichromate



M-600	Quickfuel Marine Carburetor - 600CFM Black
112-20	Throttle Body Kit - 4160 600CFM
112-9	Throttle Body Kit - 4160 750 CFM
112-117	Throttle Body Kit - Classic 850 CFM
112-115	Throttle Body Kit - Street Avenger 770 CFM

Further investigation may narrow the scope of potentially impacted products. We are inspecting carburetors in our finished goods inventory that were manufactured within the preliminary date range listed above and will confirm that the secondary throttle lever meets dimensional requirements before shipment. Validated products will be marked with a green dot on the round boss above the part number for tracking purposes.

For now, we request that you immediately quarantine all parts identified on that list. After you have completed this review, please notify us of the number of potentially impacted carburetors that you have quarantined. We will then partner with you to determine the best way to investigate and address these items.

After we have concluded our investigation, we will notify you of the confirmed scope and date range associated with this issue, and of any further actions that may be necessary.

We understand that this is an unfortunate situation and are working to minimize impact to our valued customers. If you have any questions, please contact your Holley sales director. Thank you for your continued support.

Sincerely,

John Nelligan
SVP, Sales